Dart Aerospace Ltd. Monday, 06/11/2006 9:20:30 AM Linda Lacelle User: **Process Sheet** : D412-664-203 : CC-DAR01 Dart Aerospace Ltd. **Drawing Name** Customer Job Number : 29275 **Estimate Number** : D412664203 **Part Number** P.O. Number S.O. No. : HM : 06/11/2006 **Drawing Number** NCR 095 This Issue :NIA **Project Number** Prsht Rev. : LANDING GEAR Туре **Drawing Revision** First Issue : 29190 Material **Previous Run** 13/11/2006 Qty: 1 Um: **Due Date** Written By Checked & Approved By Comment **Additional Product** THE POLICE PROPERTY OF THE PARTY OF THE PART TRANSPORT CANADA A PRIOVAL + 000-00 **CHG003** D412-664-203 Job Number: SH01-9 Crosstube Aft High SR01298NY Sic LOÏ B27391 SIC Description Model Bell 412 **Machine Or Operation:** Seq. #: MADE IN CANADA PACKAGING RESOU PACKAGING 1 1.0 **Comment: PACKAGING RESOURCE #1** REMOVE FROM STOCK D412-664-203 RECORD B/N'S B27391 \$ 06.10.27 LANDING GEAR RESOURCE 1 LANDING GEAR 1 2.0 Comment: LANDING GEAR RESOURCE 1 **REMOVE SUPPORT D2896-1** FROM CROSSTUBES AND LABEL SUPPORT 06-11-01 WITH B/N OF CROSSTUBE IT CAME OFF OF LANDING GEAR RESOURCE 1 3.0 LANDING GEAR 1

Comment: LANDING GEAR RESOURCE 1

REMOVE CENTRE ABRASION STRIP

AND CLEAN OFF ALL ADHESIVE RESIDUE

06-11-01

Each

Monday, 06/11/2006 9:20:30 AM Date: User: Linda Lacelle **Process Sheet Drawing Name: D412-664-203** Customer: CC-DAR01 Dart Aerospace Ltd. Job Number: 29275 Part Number: D412664203 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP 4.0 11.01 Comment: INSPECT WORK TO CURRENT STEP SPRAY PAINTING 5.0 SPRAY PAINTING Comment: SPRAY 06 11 13 **RE-PAINT SECTION OF CROSSTUBE** BETWEEN THE TWO CHAFING SHIELDS AS PER QSI 005 QC14 Inspect Spray Paint 6.0 **Comment:** Inspect Spray Paint 7.0 LANDING GEAR LANDING GEAR RESOURCE 1 Comment: LANDING GEAR RESOURCE 1 **INSTALL SUPPORT D2896-1** USING MAGNOBOND 6398 B MIOシーろフ **ENSURING B/N MATCHES CROSSTUBE** AS PER DSI 9357 2 X MS21920-30 B M 101568 REPLACE CLAMPS ADD RUBBER CUSHION > 2 X D2182B (D2182B058) B MS2192030 clamp(per MIL-DTL-8783C) 8.0 101568 Comment: Qty.: Total: 2.0000 Each(s)/Unit 2.0000 Each(s) clamp(per MIL-DTL-8783C) 9.0 D2182B Neoprene Cushion-.750 bl 28/11/2 Comment: Qty.: 0.9600 f(s)/Unit Total: 0.9600 f(s)Neoprene Cushion-.750 bl

Monday, 06/11/2006 9:20:31 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: D412-664-203 Customer: CC-DAR01 Dart Aerospace Ltd. Part Number: D412664203 Job Number: 29275 Job Number: Machine Or Operation: **Description:** Seq. #: INSPECT WORK TO CURRENT STEP 10.0 QC5 Comment: INSPECT WORK TO CURRENT STEP DIMENSIONAL CHECK 11.0 QC6 Comment: DIMENSIONAL CHECK PACKAGING RESOURCE #1 12.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 REPACKAGE PER PPP FINAL INSPECTION/W/O RELEASE 13.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE U 06.(1.21 Job Completion



	DESIGN	3	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAD	
	CHECKE	D #	APPROVED #	DRAWING NO. DSI 9357	REV. A SHEET 1 OF 2
1	DATE	1 40	<u> </u>	TITLE	SCALE
	06.10.25			CROSSTUBE SUPPORT CHANGE	NTS
	Α		06.10.25	NEW ISSUE	

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D212-664 Rev. C AND INSTRUCTIONS FOR CONTINUOUS AIRWORTHINESS ICA-D212-664 Rev. 2

REF. CANADIAN STC: SH01-9 REF. FAA STC: SR01298NY

For D412-664-203 Aft Crosstubes at CHG 002 or later, the D2856-600-1087 Abrasion Strip has been removed, the center D2896-1 Support has been bonded onto the crosstubes using Magnobond 6398 and D2182B058 Rubber Cushions have been installed underneath the MS21920-30 Clamps. Amend Parts List of IIN-D212-664 Section 5 and ICA-D212-664 Section 32.8 as follows:

Remove:

item	QTY -203	Part Number	Description
32	1	D2856-600-1087	ABRASION STRIP

Add:

Item	QTY -203	Part Number	Description
41	2	D2182B058	RUBBER CUSHION

To prevent the center support from shifting on D412-664-203 Crosstubes at CHG 001, the D2896-1 Support should be removed and re-installed as follows:

- 1) Follow section 32.1 of ICA-D212-664 for the removal of the crosstubes from the helicopter.
- 2) Remove the qty(2) MS21920-30 Clamps from the crosstube that fasten the D2896-1 Supports to the crosstube.
- 3) Remove the D2856-600-1087 Abrasion Strip from the crosstube per section 32.5 of ICA-D212-664.
- 4) Inspect the crosstube surface underneath the support for corrosion and mechanical damage per items 5.3.1 and 5.3.2 of the 300 hour inspection. Repair damage within acceptable limits per item 5.3.3 of the 300 hour inspection. Touch up finish per item 5.3.9 of 300 hour inspection.
- 5) Apply a 0.03" to 0.06" thick layer of Magnobond 6398 underneath D2896-1 Support and re-install the Support on the crosstube as shown in Figure 1. Use rocker beam assembly to properly align the D2896-1 Support. Ensure the Rocker Beam Assembly can move freely without any friction with other parts. Install a D2182B058 Rubber Cushion on each MS21920-30 Clamp. Position and secure the D2896-1 Support on the crosstube using MS21920-30 Clamps. Torque clamps 80-100 in lb. Let the D412-664-203 Crosstube Assembly cure before re-installing the crosstube or the aircraft.
- Re-install the D412-664-203 crosstube per section 32.2.5 through 32.2.9 of ICA-D212-664.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED


D. SHEPHERD (DE # 02)

DATE: CERT. NO.: ISSUE: 06.10.25 SH01-9

Copyright © 2006 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.









FIGURE 1 - CROSSTUBE SUPPORT INSTALLATION ON D412-664-203



Copyright © 2006 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.